

Version 18.0

Build	Module	Description	ID
23.02.18	General	Program maintenance and support	12360

Version 17.0

Build	Module	Description	ID
23.01.17	General	The concrete quality could not be selected for the calculation according to DIN EN.	10210
23.01.17	Output document	A negative value was issued for the selected concrete quality.	10707
23.01.17	User interface	The possibility to enter a partial safety factor for the lateral bedding has been removed.	10807

Version 16.0

Build	Module	Description	ID
21.01.16	General	Program modifications for the compatibility with Windows 10 .	9524

Version 15.0

Build	Module	Description	ID
30.01.15	General	Program maintenance and support	8694

Version 14.0

Build	Module	Description	ID
21.01.14	General	Program maintenance and support	7493

Version 13.0

Build	Module	Description	ID
12.03.13	General	Now, the release notes are available in English .	6444
12.03.13	General	Program modifications for the compatibility with Windows 8 .	6355