

Version 19.0

Build	Module	Description	ID
25.04.19	General	Program maintenance and support	13460

Version 18.0

Build	Module	Description	ID
23.02.18	General	Program maintenance and support	12360

Version 17.0

Build	Module	Description	ID
23.01.17	General	The concrete quality could not be selected for the calculation according to DIN EN.	10210
23.01.17	Output document	A negative value was issued for the selected concrete quality.	10707
23.01.17	User interface	The possibility to enter a partial safety factor for the lateral bedding has been removed.	10807